

RSLU Detail Report For 0057-0

16 September 2020

Authorisation Number 0057-0
Local Authority South Taranaki District

Classifications

Anzsic Division Manufacturing
Anzsic Subdivision Petroleum, Coal, Chemical and Associated Product Manufacturing
Anzsic Group Petroleum Refining
Anzsic Class Petroleum Refining

Location

Common Address Palmer Road Kapuni
River (Catchment) Kapuni (Kapuni)
Map References

Q20:102-914 1:50000 Topo Map
VNZ Legal Desc PT LOT 1 DP 13121
Valuation Ref 12231 143 - 0

Parameters

Classification	Chemical Processing/Manufacturing
Confirmation of Status	1(b)-Haz Subs Present-Risk acceptable for land use
Land Use	Commercial/Industrial
RSLU Classification	Chemical Processing/Manufacturing
RSLU Classification	Fertiliser Storage or Distribution

General Comments

Entered By: DBusing
Date: 12.7.93
Updated By: W McLarin
Date: 16.9.97 & 3.5.00
Updated by: M O'Rourke
Date: 3.08.04

Known Owners & Occupiers:
Ballance Agri-Nutrients Kapuni Limited
Petrochemical Corporation of New Zealand Ltd
Natural Gas Corporation of New Zealand Ltd

Ammonia and Urea Plant, Kapuni

Location Of Information On This Site:
SOMP 81-93
TRC Annual Reports

Tonkin and Taylor Ltd (1986) Petroleum Corporation of New Zealand Ammonia-Urea Plant Kapuni - Groundwater Hydrology Study Stage I Report Data Review, November 1986.
Tonkin and Taylor Ltd (1987) Petroleum Corporation of New Zealand Ammonia-Urea Plant Kapuni - Groundwater Hydrology Study Stage II/III Final Report, June 1987. (Ref 7586)
Tonkin and Taylor Ltd (1990) Petroleum Corporation of New Zealand Ammonia-Urea Plant Kapuni - Report on nitrate contamination of groundwater south of effluent spray out area. March 1990. (Ref 10056)
Tonkin and Taylor Ltd (1993) Petrochem Ltd. - Groundwater Investigations Stage I Report. October 1993. (Ref: 11783)

Discharge Consents Issued By TRC or TCC:
0597-2 Wastewater and contaminated stormwater discharge
0598-2 Stormwater and wastewater discharge
1766-2 Stormwater and wastewater contingency discharge
3967-1 Wastewater discharge
4046-2 Air discharge

RSLU Detail Report For 0057-0

16 September 2020

4719-1 Take and use groundwater

0015WLL Installation of groundwater monitoring bores.

Known Spillages On Property:

UIR9596221 leak from holding tanks, high strength ammonia/ urea.

UIR 9697188 leak through FECB liner.

There may be other records of incidents, consents or reports associated with this site held by Taranaki Regional Council.