

Annual Monitoring Report for Methyl
Bromide Fumigations

Site: Metro Port, Neilson Street,
Onehunga, Auckland:
May 1 2011- Dec 31 2011

Fumigation Site

Metro Port, Neilson Street, Onehunga, Auckland

Report Prepared By

Mike Goss

Report Checked By

Gerhard Van Niekerk

1. Type and number of fumigations using MB on the above site 1 May 2011 – 31 Dec 2011

| <i>Type of contained space fumigated</i> | <i>Number of fumigations</i> |
|--|---------------------------------|
| <i>Ships Holds</i> | <i>0</i> |
| <i>Containers</i> | <i>46 x 20Ft and 850 x 40Ft</i> |
| <i>Tent</i> | <i>0</i> |
| <i>Total</i> | <i>896</i> |

2. The Total amount of Methyl Bromide applied at the above site

| |
|---|
| <i>Total amount of Methyl Bromide used (kg)</i> |
| <i>6,179</i> |

3. Location on Site and Equipment used to carry out the Monitoring of Methyl Bromide

3i Portable monitoring equipment held by Genera.

3ii Genera Ltd use Ibrid (Model MX6) portable handheld monitors which measure down to 0.5ppm.

4. Annual Methyl Bromide Exposure Levels

No measureable Methyl Bromide was detected during the surveillance period.

5. Methyl Bromide Discharge – defined as “Unintentional release “ at above site

Nil

6. Number of notifications of breaches of the TEL values at the above site

Nil notifications for the period

7. If any breaches occurred list the discussion of breaches of the TELs and the remedial actions

“No breaches occurred therefore no-record of discussions of these breaches.”

8. Any other issues / accidents or non-compliance matters occur at the above site.

Nil