

Annual Monitoring Report for:
Methyl Bromide Fumigations

Site: Metroport, 339 Neilson St,
Onehunga, Auckland

Period: May 1 2011-Dec 31 2011

Fumigation Site

Metroport
 339 Neilson Street,
 Onehunga, Auckland

Report Prepared By

Amber Barron
 Account Manager,
 Rentokil Pest Control - Fumigations

Report Checked By

Rowan Washer
 National Fumigations Manager, Rentokil - Initial

**1. Type and number of fumigations using MB on the above site between the period:
 May 1 2011 – December 31 2011**

<i>Type of contained space fumigated</i>	<i>Number of fumigations</i>
Containers	231
Tent	0
Total	231

2. The Total amount of Methyl Bromide applied at the above site

<i>Total amount of Methyl Bromide used (kg)</i>	
MB in kgs	1076.6

3. Location on Site and Equipment used to carried out the Monitoring of Methyl Bromide

- 3i Location – The fumigation area is in a designated fumigation area in the middle of the container park.
- 3ii Equipment – This is a ToxiRae which reads VOC's in PPM to a minimum limit of 0.1 decimal point, the wind direction is determined by using a wind vane and compass plus the speed is determined by an anemometer.

4. Annual Methyl Bromide Exposure Levels

No measureable Methyl Bromide was detected during the above surveillance period

5. Methyl Bromide Discharge – defined as “Unintentional release “ at above site

Nil

6. Number of notifications of breaches of the TEL values at the above site

Nil

7. If any breaches occurred the discussion of breaches of the TELs and the remedial actions are list below:

No breaches occurred therefore no-record of discussions of these breaches.

8. Any other issues / accidents or non-compliance matters occur at the above site.

No Issues